





(2)「開発ツールダウンロード」をタップ (3) No. 1000 のファイル名を長押し (4)「リンクをダウンロード」





(7)この警告がでたら「設定」(警告無しで(10)に移ることもあります)







14:46 0 ♠ P	3 ★ € 60%		14:46 0 ■ ♣ ₽ (🏠 BGX-6614	* ▼ ■ 60% LIST SHOW
ログ記録中 🏅	BLE接続		ログ記録中 🍝 🛙	BLE接続
GR/GP 10 2 液晶表示 6 2 周期 1msec 2 闧値 30 2 経度 0°0'0" 約 標高 0m	本体番号 100 記録数 15639 記録間隔 2min 応答周波数 100hz 湿度 51% 緯度 0°0'0"	LIST HIDE → ← LIST SHOW	() () Xpeek -2.40	G
Xpeek -	2.40G		Ypeek -1.30	G
Ypeek -	1.30G		Zpeek -3.60	G
Zpeek -	3.60G			
x 4 00E8	RSSI -46dBm		z 4 F6DC RS	SI -47dBm
۹ •			۰ ا	

Action Barの「LIST HIDE」「LIST SHOW」でデーター覧の表示を切り替えます

開発環境のデザイン画面の「Nexus5」では LISTを非表示にすればZ軸は切れない。 実機動作は未確認。

10:00	10:00
GR/GP 10 本体番号 100 液晶表示 6 記錄数 65535 周期 1msec 記錄間隔 2min 閾値 30 応答周波数 100hz 温度 22.2°C 湿度 50% 経度 138°00'0' 緯度 35°00'00' 標高 3776m Yach	Xpeek Ypeek
Ypeek	Zpeek
Zpeek	